

# CHANGE OF PTO DRIVE SHAFT STANDARD

## DIN EN12965

Due to the existing accident situation, the standard for the main PTO drive shaft (EN12965: 2009) was revised. This results in some changes that must be implemented by the PTO drive shaft manufacturers in order to increase the safety of the PTO drive shafts.

One of the main changes is based on a new test procedure for the locking systems on yokes. Some locking systems on PTO drive shafts without a coupling on the machine side (PIC side) may no longer be used.

You are receiving this technical information because your PTO drive shaft has to be changed due to the changes described in the standard. We therefore ask you to check and approve the shown dimension "L" of the new locking system for your application.

